Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080143-5

RECEIVING INSPECTION REPORT

HYCON MFG. COMPANY

2961 E. COLORADO ST., PASADENA, CALIF.

No. 11442

RECEIVED FROM PLANT #9

DATE REC'D 3-4-57

P.O. NO.

VENDOR PACKING SLIP NO.

| CHANGE TO | CONTRACT CODE NO. | DRAWING NUMBER | DWG. DASH OR STANDARD PART NO. | DWG. REV. | LOT NO. | CLASS NUMBER | OPER. NUMBER | BUY OUT CODE NO. | O R F | ACCT. OR W.O. NO. / S.O. NO. |
|---|---|---|---|---|---|---|---|---|---|---|
| | 322 | 0 | 26 | 0 | 21 | | | | | |

| QUANTITY RECEIVED | DRAWING NO. AND DESCRIPTION | QUANTITY ACCEPTED | QUANTITY REJECTED | REMARKS |
|---|---|---|---|---|
| 84 | 738312 Latch Assembly | 84 | ✓ | |

RECEIVED BY [signature] HMC-1068

INSPECTED BY [signature] DATE 3/4/57

REJECTS RETURNED ON SHIP. MEMO NO.

RECEIVING INSPECTION REPORT

HYCON MFG. COMPANY

2961 E. COLORADO ST., PASADENA, CALIF.

No. 11475

RECEIVED FROM PLANT #9

DATE REC'D 3-7-57

P.O. NO.

VENDOR PACKING SLIP NO.

| CHANGE TO | CONTRACT CODE NO. | DRAWING NUMBER | DWG. DASH OR STANDARD PART NO. | DWG. REV. | LOT NO. | CLASS NUMBER | OPER. NUMBER | BUY OUT CODE NO. | O R F | ACCT. OR W.O. NO. / S.O. NO. |
|---|---|---|---|---|---|---|---|---|---|---|
| | 322 | 0 | 13 | 0 | 20 | | | | | |

| QUANTITY RECEIVED | DRAWING NO. AND DESCRIPTION | QUANTITY ACCEPTED | QUANTITY REJECTED | REMARKS |
|---|---|---|---|---|
| 6 | 738263 Wiring Assembly Tension Leasing | 6 ✓ | | |

RECEIVED BY [signature] HMC-1068

INSPECTED BY [signature] DATE 3/7/57

REJECTS RETURNED ON SHIP. MEMO NO.

Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080143-5